
Fatshark Connector 2 Devo 10 Trainer port



Setup New Model. PPMin – Channel. Center PW = 1500 Delta PW = 400. Trainer SW = Gear1. PPM1 – 4 = None. PPM5 &6 = CH5 & 6. PPM7 & 8 = None

