

T8SG V2 Plus on Deviation 5.0

- RELEASE NOTE -

2020-12-02

| [custom] | | [FR] | | |
|----------|---------|---------------------------------|----------|----------------------|
| Type | # | Label | Duration | Change reason |
| NEW | 267 | maintien des gaz | 1560 | was missing FR |
| NEW | 268 | relâchement de l'accélérateur | 2260 | was missing FR |
| RENAMED | 323 | formateur | 1220 | wrong translation |
| RENAMED | 324 | mode entrainement | 1320 | wrong translation |
| NEW | 358 | chronometre désactivé | 1770 | requirement |
| NEW | 359 | chronometre activé | 1790 | requirement |
| NEW | 360 | minuteur désactivé | 1690 | requirement |
| NEW | 361 | minuteur activé | 1610 | requirement |
| CHANGE | 267-361 | #number +2 added from 261 to361 | 269-363 | Due to EN Alignement |

| [custom] | | [EN] | | |
|----------|---------|---------------------------------|----------|-----------------------|
| Type | # | Label | Duration | Change reason |
| NEW | 292 | flight mode 7 | 1220 | was missing EN |
| NEW | 355 | starter off | 1220 | was missing EN |
| NEW | 356 | starter on | 1220 | was missing EN |
| NEW | 357 | light off | 1220 | was missing EN |
| NEW | 358 | light on | 1220 | was missing EN |
| NEW | 359 | stopwatch disabled | 1220 | requirement |
| NEW | 360 | stopwatch activated | 1220 | requirement |
| NEW | 362 | timer off | 1220 | requirement |
| NEW | 361 | timer activated | 1220 | requirement |
| CHANGE | 292-361 | #number +1 added from 292 to361 | 293-363 | Due to EN Missing 292 |

Script available to change the voice.ini config file quickly. Local INI file for model must be update as well.